



EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM
GANGTOK

Memo No. - 916/2023/EDN.

Date - 07/06/2023


BUILDING SAFETY CERTIFICATE

This is to Certify that a physical inspection of **Kendriya Vidyalaya N.H.P.C Singtam**, in **East Sikkim**, was conducted on 07th June 2023 by the field engineer of Education Department East-I, where it was found that the above mentioned school has a single building which comprises of two storeyed RCC structure, used for academic purposes having 40 classrooms with 2 toilets for Boys & Girls on each floor. The built in plinth area is 77,885.28ft².

The visual inspection revealed that the columns, beams and slab had no cracks or shear stress of any kind, the partitions were also found to be free from cracks. Till date the School building have no significant damages and defects. Hence, the structure can be certified to be fairly safe.

This certificate is valid for a period of one year only from the date of issue.

~~Assistant Engineer, East-I
Education Department
Govt. of Sikkim~~
Assistant Engineer
Education Department
Govt. of Sikkim


Divisional Engineer
East-I
Education Department
Govt. of Sikkim